



Method Statement Update for Covid-19

Date 10-06-2020

When working in depots

Ensure social distancing is observed at all times make sure you have the correct PPE required . Wash you hands regularly . clean the equipment you have used. Make sure surfaces in depot are kept cleaned .

When working on customers sites.

Upon arrival at site apply PPE as required book in with customer maintaining social distance of 2.5 meters as per government guidelines . ask the customer to put the truck in a area which you can maintain a social distance of 2.5 metres cone the area off. Ensure safe routing of electrical cables

No one other than the fitter doing the job should be within the area coned off during the job .

Upon completion of the job

Clean the work area also and equipment put tooling back in the van remove the cones advise the customer the truck can be collected. Wash your hands or sanitise leave site.